



HEAVING SIDEWALKS



LACK OF COHESIVE FURNITURE PALETTE




INFLUX OF BIKES AND SCOOTERS ON SIDEWALK



MISSING TREE CANOPY



IMPERVIOUS TREE PIT CONDITION



OPPORTUNITY FOR CURB EXTENSIONS AT CORNERS



LACK OF BICYCLE INFRASTRUCTURE



LOADING ZONES



LONG PEDESTRIAN CROSSINGS



MIDBLOCK CROSSINGS



CROSSWALKS IN POOR CONDITION



MISALIGNED CURB RAMPS