
Middle Street, Brockham Collision Data Analysis

(Recorded 10yr period between 2012 – 2022 at time of initial research and conception of scheme)



October 2013 – outside cottages

Shunt collision into rear of parked vehicle during the day (10:02am)

Recorded collision: Slight

STATS19 Police report:
V2 PARKED. V1 HIT V2 IN THE REAR.

No further information available in the STATS19 Police report

March 2014 – outside cottages

Loss of control collision into rear of parked vehicle during the day (12:15pm)

Recorded collision: Slight

STATS19 Police report:
V1 LOST CONTROL LEFT CARRIAGEWAY TO NS COLLIDING WITH ROADSIDE FURNITURE AND GATE TO 95 MIDDLE STREET.

Note: It is thought that there must have been an obstruction (parked vehicle or a manoeuvring vehicle) in the southbound running lane. Driver may have been attempting to pass the obstruction and misjudged the distance of oncoming northbound traffic and has had to take avoiding action, resulting in a loss of control collision and conflicting with roadside street furniture. This cannot be confirmed, although it is unusual for a vehicle to suddenly lose control of a vehicle on a straight road with good visibility.

July 2018 – outside cottages

Shunt collision into rear of parked vehicle during the hours of darkness (licenced taxi driver) (00:25am)

Recorded collision: Serious

STATS19 Police report:
V1 TRAVELLING SOUTH ON MIDDLE STREET. FOR AN UNKNOWN REASON V1 HAS HIT V2 WHICH WAS PARKED ON NEARSIDE. V1 HAS LOST CONTROL AND HIT THE OFFSIDE KERB WHERE IT STOPPED. V2 HAS SPUN AND HIT METAL RAILINGS.

Also reported to SCC via residents



January 2019 – outside cottages

Shunt collision into rear of parked vehicle during the hours of darkness
(21:40pm)

Recorded collision: Serious

STATS19 Police report:
V1 HAS BEEN TRAVELLING ON A SINGLE UNLIT CARRIAGEWAY AND COLLIDED WITH V2 WHICH WAS PARKED AT THE NEARSIDE OF THE ROAD WHICH HAS INTURN IMPACTED WITH V3 ALSO PARKED AT THE NEARSIDE OF THE ROAD.

Also reported to SCC via residents



January 2022 – outside cottages

Reported collision: damage only

Hit and run shunt collision into rear of parked vehicle during the hours of darkness
(time unknown)

Reported to SCC via residents

1 of 2





January 2022 – outside cottages

Reported collision: damage only

Hit and run shunt collision into rear of parked vehicle during the hours of darkness
(time unknown)

The collision resulted in a scaffold pole being ejected from a flatbed lorry entering the cladding of the adjacent property at No103. This evidences the impact and force at which the collision occurred.

Reported to SCC via residents

2 of 2

